

DEMPSEY CONSTRUCTION COMPANY, INC.

1121 Lakeview Blvd. - HARTSVILLE, SOUTH CAROLINA 29550 - (843) 332-6466

August 6, 2020 Revised February 2, 2021 Revised April 6, 2021

Mr. Russ Slatton Stephen Wild City of Hartsville 100 E. Carolina Ave. Hartsville, S C 29550

Re: COH Lawton Park Pier Repair Pricing 2020

Dear Stephen,

Dempsey Construction Company is pleased to price repairing the pier at Lawton Park. The pricing is based on a site visit, and experience on pier systems.

I have included a descriptive attachment showing the repair process with total cost. After your review, please indicate any corrections if needed, as this could change the current pricing. If all is in order, I will be glad to produce a contract proposal or accept a Purchase Order.

I am available for discussion at your convenience and look forward to hearing back from you.

Sincerely,

Winthrop A. (Windi) Dempsey Vice President Dempsey Construction Co. Inc., Office (843) 332-6466

Fax (843) 332-1841 Cell (843) 858-4138

Email dempseyconstructionco@sc.twcbc.com

DEMPSEY CONSTRUCTION COMPANY, INC.

1121 Lakeview Blvd. - HARTSVILLE, SOUTH CAROLINA 29550 - (843) 332-6466

Attachment

(COH Lawton Park Pier Repair Pricing 2020) 8-6-2020 Revised 2-2-2021 Revised 4 6 2021

Pier Repair Pricing

Orig. Total = \$28,800.00

Mat. Increase Feb2021 + \$1,800.00

Revised Total = \$30,600.00

Mat. Increase April2021 + \$3,000.00

Revised April Total = \$33,600.00

Note: Pricing honored 30 days from April 6, 2021. Work can be installed the end of May if scheduled timely.

Note: An inspection was made to the existing pier to determine a basis for what should be saved. In determining this, we evaluated what was visible and any items hidden would not be included.

Description

Pier Components Include:

Land entrance platform 5'W x 9'L w/ Main Pier run 6'W x 82'L (RR) Removed and Replaced, (K) Keep, (Adj.) Adjust, (A) ADD new

Land Entrance Platform 5'W x 9'L

• (RR) Remove and replace entirely

Main Pier Run 6'W x 82'L

- Pilings / Post
 - o (K) Keep all existing
 - o (A) Add new stabilizer/bracing posts
 - 6-16' post / 2sets each section starting at end thru 3rd section back
 - 6x6 #2 grade, ground contact treatment
- Pile Caps or Cross Beams mounted to post by bolts that support stringers
 - o (K) Keep
 - o (Adj.) Adjust / reset bolting into new mounting points
- Stringers / Walk Board Joist
 - o (RR) Remove and replace
 - o 2x8 #2 grade, ground contact treatment
- Walk board decking
 - o (RR) Remove and replace
 - o 2x6 #1 grade, kiln dried after treatment
- Handrail vertical post
 - o (Adj.) Adjust / reset bolting
 - o (K) Keep, pressure wash to look new
 - 4x6 members
- Handrailing, top/ and mid horizontal rails
 - o (RR) Remove and replace
 - o 2x6, #2 grade ground contact treated
- Pressure wash existing items to look new

Note: Pricing Honored for 30 Days / 20% Deposit / 40%2nd Draw @50% complete / 40% Final